

Reduce set-up times up to 80% for maximum productivity.

ZEISS FixAssist® CT



Reduce machine downtime by shortening set-up times.

Faster set-up. Higher productivity.



Get the most out of your machine and drive productivity. With ZEISS FixAssist CT the workpiece is adjusted outside the machine on the pallet before the measurement. The pre-aligned workpiece can then be placed within the CT in seconds. Shortening set up times and saving money!

Optimize accuracy. Extend service life.



During set-up, the simulation of the CT beam path ensures that the component is completely within the beam path. This reduces faulty measurements and optimizes measurement accuracy. FixAssist CT also extends the service life of the X-ray tube due to avoiding run-up cycles when pre-aligning workpieces outside the machine.

Flexible. Easy to use.



The new user interface is intuitive and easy to use. New software and functions record the entire measuring volume at a glance.



Find out more or request
an offer in our shop.

SHOP

INFO

Ensure 100% utilization of your Metrotom

