


Corona extreme - Service Parts



The following spare parts are available for the lamp replacement of the Corona extreme. Afterwards a lamp calibration is necessary. The required equipment is listed below.

Description	Order Number	List Price [Euro]
Service Kit Corona extreme	000000-2425-664	5,520.00
Spare parts kit for lamp exchange Rev.1	000000-2397-831	231.00
Spare parts kit for lamp exchange Rev.2	000000-2397-832	503.00
Spare parts kit for lamp exchange Rev.3	000000-2402-119	362.00