


## Corona extreme - Service Parts



The following spare parts are available for the lamp replacement of the Corona extreme. Afterwards a lamp calibration is necessary. The required equipment is listed below.

Description	Order Number	List Price [USD]
<b>Service Kit Corona extreme</b>	000000-2425-664	6,900.00
<b>Spare parts kit for lamp exchange Rev.1</b>	000000-2397-831	346.00
<b>Spare parts kit for lamp exchange Rev.2</b>	000000-2397-832	754.00
<b>Spare parts kit for lamp exchange Rev.3</b>	000000-2402-119	544.00